

ga - Watthour and Watthour-Demand Meters
Solid State Registers

Manufacturer	Conditions
<u>Electro Industries/GaugeTech</u> NEXUS 1262 Form 9S, Class 20 NEXUS 1272 Form 9S, Class 20	To obtain experience.
<u>Elster</u> Solid State Polyphase Watthour meter, Alpha line, A1, A and S type bases (all forms) Class 20 and 200, 120, 240, 277, and 480 V	To obtain experience.
<u>GE</u> kV Vector Meter Form 10A, 36A, 45A, 48A, 3S, 9S, 36S, 45S 56S; Class 20; 120 V to 480V or 57V to 120V Form 13A, 16A; Class 150; 120V to 480 V Form 2S, 12S, 16S; Class 200 or 320; 120V to 480V	To obtain experience.
<u>Invensys</u> Socket base, 3 wire, single-phase watthour meter, Type iS01, Class 200	To obtain experience.
Socket base, 3 wire, single-phase watthour meter, Type iSA1 Class 200 with integrated Itron 51ESS ERT	To obtain experience.
Socket base, 3 wire, single-phase watthour meter, Type iN01 Class 200 Electronic Network Meter.	To obtain experience.
Socket base, 3 wire, single-phase watthour meter, Type iNA1 Class 200 iCon Network Meter with Integrated AMR	To obtain experience.
<u>Itron Inc.</u> SENTINEL Forms 9S, 10A, 45A, 45S, 46A, 46S, 48A, 66S Class 20 Form 16A Class 150 Forms 2S, 12S, 16S Classes 200 and 320	To obtain experience.

ga - Watthour and Watthour-Demand Meters
Solid State Registers

Manufacturer	Conditions
<u>Landis+Gyr</u>	
Solid State Watthour Meter Type DDS2, Form 5S, 6S, 8S, 9S, 10S, Class 20.	To obtain experience.
<u>FOCUS</u>	
Form 1S, Class 100	
Form 25S, Class 200	
Form 2S, Class 200TA30 and 200TA50	
Form 2SE, Class 320TA30 and 320TA50	
Form 2K, Class Class 4800/600	
Form 3S, 4S, Class 10 and 20	
<u>Altimus Solid State Meter</u>	
Form 1S, Class 100	
Form 25S, Class 200	
Form 2S, Class 200TA30 and 200TA50	
Form 2SE, Class 320TA30 and 320TA50	
Form 2K, Class 480/600	
Form 3S, 4S, Class 10 and 20	
<u>S4 Polyphase Solid State Meter</u>	
Form 5S/45S, 6S/36S, 9S/8S, Class 20	
Form 12S, 16S, Class 200	
<u>Power Measurement</u>	
<u>ION 8300</u>	
Form 9S, 35S, 36S Class 20	To obtain experience.
<u>ION 8400</u>	
Form 9S, 35S, 36S, 39S, 76S Class 20	To obtain experience.
<u>ION 8500</u>	
Form 9S, 35S, 36S, 39S, 76S Class 20	To obtain experience.
<u>Schlumberger</u>	
<u>CENTRON</u>	
Form 2S, Class 200.	To obtain experience.
Solid State or Mechanical Register.	
<u>FULCRUM SQ400</u>	
Form 5A, 6A, 9A, 5S, 6S, 9S, 10S, Class 20	To obtain experience.
<u>FULCRUM SL300 Series</u>	
Form 5A, 6A, 8A, 9A, 5S, 6S, 8S, 9S, 10S, 12S, 14S, 15S, 16S, Class 20 and 200.	To obtain experience.
<u>QUANTUM Q200 Series</u>	
Form 5A, 6A, 8A, 9A, 5S, 6S, 8S, 9S, 10S, 26S, Class 20 and 200.	To obtain experience.
<u>QUANTUM Q300 Series</u>	
Form 6A, 9A, 6S, 9S, 10S, Class 10 and 20.	To obtain experience.
<u>VECTRON SVX</u>	
Form 5A, 6A, 8A, 10A(9A), 5S, 6S, 9S(8S), 12S, 16S(14S, 15S), 26S, Class 20 and 200.	To obtain experience.

ga - Watthour and Watthour-Demand Meters
Solid State Registers

Manufacturer	Conditions
<u>Transdata, Inc.</u> MARK-V EMS Form 5S, 5A, 6S, 6A, 8S, 8A, 9S, 9A Class20	To obtain experience.